


Heating Jacket

The heating jacket is available for all magnetic drive GATHER gear pumps and centrifugal pumps. By a forced internal flow of heating fluid the heating jacket guarantees that the pump head is heated uniformly. The heating jacket can be easily mounted onto the pump head.



Technical Data:

- heating connections G 1/4
- stainless steel casing 1.4571
- pressure in heating shell up to 20 bar
- heating / cooling fluid:
brine, steam, thermal oil etc.
- heating temperature up to +400°C

Attention: If the heating jacket will be isolated by the user, the connection parts to the motor **must not** be isolated.